



**LEGEND**

- Development Footprint / Clearing Application Area
- Native Vegetation to be cleared
- Rehabilitated
- Road Reserve
- Vegetation Condition within the Development Footprint**
- Very good
- Good
- Cleared
- Habitat Trees within the Development Footprint**
- Eucalyptus occidentalis***
- Class 5
- Eucalyptus wandoo***
- ▲ Class 5

Vegetation Type	Extent (ha)	% of DF
Good	0.9508	16.33%
Very good	0.1390	2.39%
X	4.7342	81.29%
<b>Total (ha)</b>	<b>5.8240</b>	<b>100.00%</b>

**Shire of Cranbrook tenure - Native Vegetation to be cleared**

Land ID	Road Reserve	Good	Very good	Total (ha)
3464480	CARLISLE STREET	0.0004		0.0004
3753980	HARDY STREET		0.0976	0.0976
	<b>Total (ha)</b>	<b>0.0004</b>	<b>0.0976</b>	<b>0.0980</b>



**SHIRE OF CRANBROOK LANDS  
CRANBROOK RAIL UPGRADE  
DISTURBANCE**

**DATA SOURCES:**  
SOURCE DATA: FAUNA AND VEGETATION DATA (ECOSCAPE 2022), CADASTRE (LGATE-217) (LGATE 2023), ROAD NETWORK (MRWA 2020)  
AERIAL: ESRI BASEMAP (2020)  
SERVICE LAYERS: SOURCE: ESRI, MAXAR, EARTHSTAR GEOGRAPHICS, AND THE GIS USER COMMUNITY



COORDINATE SYSTEM: GDA 1994 MGA ZONE 50  
PROJECTION: TRANSVERSE MERCATOR  
DATUM: GDA 1994  
UNITS: METER



REV	AUTHOR	APPROVED	DATE
0	NW	NW	18/01/2023
1	NW	NW	31/01/2023

**FIGURE  
1**